

Surveyors Name LP/Suncoast	Certificate Number 02-060	System Owner Florence, MS	Survey Customer Florence, MS	Drainage Area	Sheet				
PIG No. 374	Pipeline Segment Reference 117-114	Date 5/22/2003	Time	Location (Street Name and number) 182 W Main ST	Locality Florence, MS				
Further Location details Front yard		Upstream Manhole Number 117	Rim to Invert 5.8	Grade to Invert	Rim to Grade				
Downstream Manhole Number 114	Rim to Invert 5.8	Grade to Invert	Rim to Grade	Use of Sewer Sanitary	Direction Downstream	Flow Control De-Watered using jetter	Height 8		
Width	Shape Circular	Material Vitrified Clay Pipe	Ln. Method	Pipe Joint Length 5	Total Length 546	Length Surveyed 83	Year Laid	Year Rehabilitated	Tape / Media Number 6037
Purpose Infiltration/Inflow Investigation	Sewer Category	Pre-Cleaning Jetting	Cleaned	Weather Dry	Additional Information				

